STATE OF CALIFORNIA STATE AND CONSUMER SERVICES AGENCY CALIFORNIA BUILDING STANDARDS COMMISSION 2525 NATOMAS PARK DR., SUITE 130 SACRAMENTO, CA 95833 (916) 263-0916 Phone (916) 263-0959 Fax

(916) 263-0916 Phone (916) 263-0959 Fax Email: BSC@dgs.ca.gov

Office Use Item No. _____

PARTICIPATION COMMENTS FOR THE NOTICE DATED AUGUST 22, 2006 Written comments are to be sent to the above address.

WRITTEN COMMENT DEADLINE: OCTOBER 16, 2006

			Date: October 13, 2006	<u>3</u>
From:				
	F. Thorman, AIA – State Ai lame (Print or type)	rchitect	(Signature)	
Divisi	on of the State Architect -	Access Compliance		
	Agency, jurisdiction, chap	ter, company, associat	ion, individual, etc.	
1102	Q Street, Suite 5100, Sacrar	mento, CA 95814		
Street	City	State	Zip	
/We (do)(do not) agree with: [X] The Agency proposed modifications As Submitted on Item No. DSA AC 02/06 (Part 2 – DOJ)				
and request that this	section or reference provisio	n be recommended:		
[] Approved	[] Disapproved []	Held for Further Study	[X] Approved as Amended	
by the reviewing Cod	de Advisory Committee.			

Suggested Revisions to the Text of the Regulations (Revisions Without Regulatory Effect):

- General. DSA/AC proposes to update the model code language where required throughout this document to
 match the current published 2006 International Building Code language.
 Reason: Model code language shown in this document was based on draft language made available to the
 State of California by the International Code Council. The final published model code language contains minor
 revisions or updates in various locations.
- Application. DSA/AC proposes to remove the general application statement, "for applications listed in Section 109.1 regulated by the Division of the State Architect/Access Compliance", and replace with the DSA/AC acronym, "[For DSA/AC]", where required throughout this document.
 Reason: This change is required for consistency with the Building Standards Commission format.
- Section 1116B.1.10 Hall Call Buttons. DSA/AC proposes to correct a typographical error in the last sentence of this section by inserting an approved 2004 Rulemaking change. Criteria #1 & 8.

 Page 1. An approved 2004 Rulemaking change was unintentionally emitted during proparation of this

Reason: An approved 2004 Rulemaking change was unintentionally omitted during preparation of this document. DSA/AC is proposing to insert the approved change, "Hall call buttons shall be internally illuminated with a white light over the entire surface of the button," as the last sentence of this section.

1116B.1.10 Hall Call Buttons. The centerline of the hall call buttons shall be 42 inches (1067 mm) above the

floor. Buttons shall be a minimum of 3/4-inch (19.1mm) in size and shall be raised 1/8 inch (3.2 mm) [plus or minus 1/32 inch (0.8 mm)] above the surrounding surface. The button designating the up direction shall be on top. Visual indication shall be provided to show each call registered and extinguished when answered. Objects adjacent to, and below, hall call buttons shall not project more than 4 inches (102 mm) from the wall. Hall call buttons shall be internally illuminated with a white light over the entire surface of the button.

Section 1117B.2.7 Enclosures. DSA/AC proposes to correct a conflict between the code provisions located in this section and the proposed changes to Figure 11B-4.
 Reason: In order to comply with the federal ADA Standards, Figure 11B-4 was revised. Associated revisions

to this section were inadvertently omitted during preparation of the rulemaking document. Criteria #1.

1117B.2.7 Enclosures. If telephone enclosures ...

- 1. Side reach possible. The everhang shall be no greater than 19 inches (483 mm). The height of the lowest everhanging part shall be equal to or greater than 27 inches (686 mm). Where a parallel approach is provided at a telephone within an enclosure, the enclosure and counter may extend beyond the face of the telephone a maximum of 10 inches (254 mm). The enclosure and counter may not overlap the required clear floor or ground space. See Figure 11B-4 (a).
- 2. Full-height enclosures. Entrances to full-height enclosures ...
- 3. Forward reach required. If the everhang is greater than 12 inches (305 mm), then the clear width of the enclosure shall be 30 inches (762 mm) minimum; if the clear width of the enclosure is less than 30 inches (762 mm), then the height of the lowest everhanging part shall be equal to or greater than 27 inches (686 mm). Where a front approach is provided at a telephone within an enclosure, the counter may extend beyond the face of the telephone a maximum of 20 inches (508 mm) into the required clear floor or ground space and the enclosure may extend beyond the face of the telephone a maximum of 24 inches (610 mm). If an additional 6 inches (152 mm) in width of clear floor space is provided, creating a clear floor space of 36 inches by 48 inches (914 mm by 1219 mm), the enclosure may extend more than 24 inches (610 mm) beyond the face of the telephone. See Figure 11B-4 (c).
- 4. Protruding telephone enclosures. Where telephone enclosures protrude ...
- Section 1134B.1 Scope. DSA/AC proposes to correct a typographical error following this section. Reason: The section title "CHAP. 11B, DIV. IV" should not appear in this location. Criteria #8.

1134B.1 Scope. The provisions of this division apply to ... CHAP. 11B, DIV. IV
1134B.2 General. All existing buildings and facilities ...

Section 1134B.2.2 (Accessibility for Existing Buildings). DSA/AC proposes to correct a typographical error by adding the IBC adoption proposed changes to this section. Criteria #8.
 Reason: The IBC adoption proposed changes were omitted in error.

4134B.2.2 Where it is technically infeasible in the area of an alteration to make existing restroom to the facilities code compliant and to install separate canitary toilet facilities for each sex, then the installation of at least one unisex toilet/bathroom facility per floor being altered, located in the same area as existing toilet facilities, will be permitted. Such a facility shall meet the requirements of Section 1115B.7.2.